

INVESTIGATION REPORT
BUILDING AND SAFETY/LAND DEVELOPMENT DIVISION

Location of Problem: 14864 Valley Blvd
Locality: La Puente
Description of Problem: Non permitted construction
behind church
Patio Remint

Requested by: Captain Valdez Phone: _____
Address: Sheriffs Dept.
Request call back after investigation? Yes ☐ No ☒

Received by: _____ Date: _____
Assigned/Referred to: _____ Date: _____
Report of Investigation: _____

Investigator: Herze Title: BED Date: 3/10/98
Copy Sent to: Herze Title: " Date: LI
Report Phoned to: _____ Title: _____ Date: _____

DISKAM/AM20.12A/07/95

Cleanok GAC 4/10/98

JOB

ADDRESS 14864 Valley

OWNER _____

NOTICE OF VIOLATION

The work performed is in violation of the Ordinance(s) indicated below:

<input checked="" type="checkbox"/> Building Code	<input type="checkbox"/> Plumbing Code
<input type="checkbox"/> Mechanical Code	<input type="checkbox"/> Electrical Code
<input type="checkbox"/> Grading Code	<input type="checkbox"/> Zoning Code
<input type="checkbox"/> _____	<input type="checkbox"/> _____

DESCRIPTION: now-permitted
structure along property
line behind church.
remove or provide
permits within 10 days,
and call for Insp.

☒ STOP ALL WORK

☐ Submit plans for the cited work within 10 days to the office listed above and apply for a plan check for the required permit(s).

☒ Obtain permit(s) within 10 days at the office listed above for the cited work.

☐ A referral has been made to the Enforcement Section of the Department of Regional Planning.

8-18-97

DATE

M.D. Hoyer

INSPECTOR'S SIGNATURE